



Evervolt
energy that lasts forever

Evervolt Solar Private Limited,
Regd. Office: No.331, 1st Floor, 1st Main,
5th Cross, Pipeline Road, Vijayanagar,
Bangalore, Karnataka, India, 560 040

AMC Service report

CUSTOMER NAME: The Principal
ATME College of Eng.
Mysore

DATE: 05.03.2018

EQUIPMENT: Solar ongrid inverter

MODEL/RATING: 25kVA - 4W

SR.NO: 1085KDTU168R0024 - 02

CONTACT PERSON: Mr. Mohan

BATTERY DETAILS:

CONTACT NUMBER: Ph: 9448285647

BATTERY TYPE:

PROBLEM REPORTED: Preventive Maintenance visit

STATUS: WARRANTY: yes/no AMC: yes/no OUT OF WARRANTY: yes/no PM: yes/no BREAKDOWN: yes/no

Observation & work done:

Visited the above mentioned site
& carried out Preventive Maintenance
of ongrid ~~inverter~~ inverter. During
visit checked all parameters of
inverter & charging voltage found ok.
Now all inverters are working
Satisfactory with load.

Input volts 3-0	Output volts
RY	
YB	
BR	
Input volts PN	
Output Volts PN	
Output load	
Earth neutral volts	
Charger volts	
Charging current	
JOB COMPLETED	YES: ☒ NO: ☐

CUSTOMER REMARKS: _____

Principal
ATME College of Engineering
13th KM Mysuru-Kanakapura Bangalore Road
Malahalli, Mysuru 570 024

SERVICE ENGINEER NAME: [Signature] SIGNATURE

[Signature]
CUSTOMER SIGNATURE & SEAL



Evervolt
energy that lasts forever

Evervolt Solar Private Limited,
Regd. Office: No.331, 1st Floor, 1st Main,
5th Cross, Pipeline Road, Vijayanagar,
Bangalore, Karnataka, India, 560 040

AMC Service report

CUSTOMER NAME: The Principal
ATME College of eng
Banner Road
Mysore

DATE: 27.02.2019

EQUIPMENT: Solar Inverter

MODEL/RATING: 25kVA - 4W

SR.NO: 102540T0162R0024

CONTACT PERSON: Mohan

BATTERY DETAILS:

0025

CONTACT NUMBER: 9448285647

BATTERY TYPE:

0026

0027

PROBLEM REPORTED: Preventive maintenance

STATUS: WARRANTY: yes/no AMC: ☒ yes/no OUT OF WARRANTY: yes/no PM: ☒ yes/no BREAKDOWN: yes/no

Observation & work done:


Visited the above mentioned site
I carried out Preventive maintenance
of Solar ongrid inverter.
25kVA - 4W.

During visit checked all electrical
parameters found ok.


Now all inverter are working
Satisfactory.


Input volts 3-0	Output volts
RY	
YB	
BR	
Input volts PN	
Output Volts PN	
Output load	
Earth neutral volts	
Charger volts	
Charging current	
JOB COMPLETED	YES: ☒ NO: ☐

CUSTOMER REMARKS: _____


PRINCIPAL

ATME College of Engineering
13th KM Mysuru-Kanakapura-Bangalore Road
Mellahalli Mysuru-570 028


SERVICE ENGINEER NAME/SIGNATURE


CUSTOMER SIGNATURE & SEAL



Evervolt
energy that lasts forever

Evervolt Solar Private Limited,
Regd. Office: No.331, 1st Floor, 1st Main,
5th Cross, Pipeline Road, Vijayanagar,
Bangalore, Karnataka, India, 560 040

AMC Service report

CUSTOMER NAME: The Principal
ATME college of eng
Bannur Road
Mysore

DATE: 13.08.2019

EQUIPMENT: Solar UPS (ongrid)

MODEL/RATING: 25kVA-44

SR.NO: 108540TU168R0024

CONTACT PERSON: Mr. Mohan

BATTERY DETAILS:

0025

CONTACT NUMBER: PH. 9448285647

BATTERY TYPE:

0026

PROBLEM REPORTED: PM visit

0027


STATUS: WARRANTY: yes/no AMC: ☒ yes/no OUT OF WARRANTY: yes/no PM: ☒ yes/no BREAKDOWN: yes/no


Observation & work done


Preventive maintenance carried out & checked all parameters of inverters found ok & cleaned the dust by using blower. Now all 44 inverters are working Satisfactorily with load.

Input volts 3-0	Output volts
RY	
YB	
BR	
Input volts PN	
Output Volts PN	
Output load	
Earth neutral volts	
Charger volts	
Charging current	
JOB COMPLETED	YES NO

CUSTOMER REMARKS


PRINCIPAL
ATME College of Engineering
13th KM Mysuru-Kanakapura-Bangalore Road
Mellahalli Mysuru-570 028

SERVICE ENGINEER NAME:  SIGNATURE


CUSTOMER SIGNATURE & SEAL



Evervolt
energy that lasts forever

Evervolt Solar Private Limited,
Regd. Office: No.331, 1st Floor, 1st Main,
5th Cross, Pipeline Road, Vijayanagar,
Bangalore, Karnataka, India, 560 040

AMC Service report

CUSTOMER NAME: The Principal
ATME College of eng.
Bannur Road
Mysore

DATE: 02.06.2020

EQUIPMENT: Solar UPS

MODEL/RATING: 25kVA - 4W

SR.NO: 1025KDT0168R0024

CONTACT PERSON: Mr. Mohan

BATTERY DETAILS:

0025

CONTACT NUMBER: PH: 9448885647

BATTERY TYPE:

0026

PROBLEM REPORTED: PM visit

0027

STATUS: WARRANTY: yes/no AMC: yes/no OUT OF WARRANTY: yes/no PM: yes/no BREAKDOWN: yes/no

Observation & work done

Visited the above mentioned site
& carried out preventive maintenance
of Solar ongrid inverter.

During visit checked all electrical
Parameters of all inverters found
OK.

Now all inverters are working
Satisfactory with load.

Input volts 3-0	Output volts
RY	
YB	
BR	
Input volts PN	
Output Volts PN	
Output load	
Earth neutral volts	
Charger volts	
Charging current	
JOB COMPLETED	YES: ☒ NO: ☐


CUSTOMER REMARKS:

Principal

ATME College of Engineering
13th KM Mysuru-Kanakapura-Bangalore Road
Mellahalli Mysuru-570 028

SERVICE ENGINEER NAME/SIGNATURE: [Signature]

CUSTOMER SIGNATURE & SEAL: [Signature]



Evervolt
energy that lasts forever

Evervolt Solar Private Limited,
Regd. Office: No.331, 1st Floor, 1st Main,
5th Cross, Pipeline Road, Vijayanagar,
Bangalore, Karnataka, India, 560 040

AMC Service report

CUSTOMER NAME: The Principal
ATME College of Eng.
Mysore

DATE: 08.05.2021

EQUIPMENT: Solar ongrid inverter

MODEL/RATING: 25kVA - 4W

SR.NO: 1085KDTU162R0024 - 02

CONTACT PERSON: Mr. Mohan

BATTERY DETAILS:

CONTACT NUMBER: PH: 9448285647

BATTERY TYPE:

PROBLEM REPORTED: Preventive maintenance visit

STATUS: WARRANTY: yes/no AMC: yes/no OUT OF WARRANTY: yes/no PM: yes/no BREAKDOWN: yes/no

Observation & work done:

Visited the above mentioned site
& carried out preventive maintenance
of ongrid ~~inverter~~ inverter. During
visit checked all parameters of
inverter.

Input volts 3-0	Output volts
RY	
YB	
BR	
Input volts PN	
Output Volts PN	
Output load	
Earth neutral volts	
Charger volts	
Charging current	
JOB COMPLETED	YES: ☒ NO: ☐

CUSTOMER REMARKS: _____

[Signature]
PRINCIPAL

ATME College of Engineering
13th KM Mysuru-Kanakapura Bangalore Road
Mallahalli, Mysuru - 570 024

[Signature]
SERVICE ENGINEER NAME / SIGNATURE

[Signature]
CUSTOMER SIGNATURE & SEAL